COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

AO67VUN

Land Rover Range Rover Sport 3.0 SDV6 306 HSE Dynamic

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present
Cap Id	67175
Cap Code	LRRS303HD5EDTA4 2

Details

Location	Doncaster	**Colour**	BLUE	**CAP Below**	£8,900.00
Reg. date	22/01/2018	**VIN**	SALWA2EK0HA180057	**Gearbox**	AUTOMATIC
Year	2018	**Body Style**	SUV	**Gears**	8
Mileage	89,826 Miles Not Warranted	**MOT Due**	30/01/2027	**Doors**	5
Fuel Type	Diesel	**CAP Clean**	£11,200.00	**Axle Combi**	4x4
GVW	3050kg	**CAP Average**	£10,050.00		

NO FRONT NUMBER PLATE, SMOKING KEYLESS IGNITION

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Navigation system
- Electric sunroof
- Drivers airbag
- Alloy wheels
- Cruise control
- Park assist camera
- Air conditioning
- Passenger airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Central locking
- Heated front seat
- Digital radio
- Rear electric windows
- Leather seat trim


Photos








15:24
11°c
38miles
089827 miles



Ignition On
38miles
089827 miles


JAGUAR LAND ROVER LTD
e11*2007/46*0909
SALWA2EKOHA180057
3050 kg
6550 kg
1- 1500 kg
2- 1775 kg
LRC J8M LOIRE BLUE




















Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Number Plate Front
Missing
Replace



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front
Poor Previous Repair
Rippled UpTo 30%



6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Chipped
Multiple Chips




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Boot Lid
Scratched
Over 25mm Thru Paint



12: Boot Lid
Scratched
Over 25mm Thru Paint



13: Lamp osr
Broken
Replace



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Chipped
Multiple Chips



18: Door osr
Dented
Over 30mm



19: Seat Base Cover osr
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK