

VEHICLE INSPECTION REPORT

HN74TGV

Ford Transit Custom 300 2.0 EcoBlue 136ps Limited

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/09/2024

Year 2024

Mileage 6,879 Miles Not Warranted

Fuel Type Diesel

GVW 3025kg

Colour SILVER

VIN WFORXXTA0RRB16310

Body Style Panel Van L2

MOT Due 29/09/2027

CAP Clean £23,950.00

CAP Average £22,600.00

CAP Below £19,850.00

Gearbox MANUAL

Gears 6

OUTSTANDING RECALL SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF


OSR


Spare

Features

- Bluetooth connection
- Park assist camera
- Front electric windows
- Central locking
- Cruise control
- Rear parking sensor
- Metallic Paint
- Cloth seat trim
- Front parking sensor
- Digital radio
- Drivers airbag
- Heated front seat
- Air conditioning
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Fuel Flap
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		